


Picture 1 Connector Looking West from Chinden Blvd.



Picture 2 Pedestrian crossing Chinden and 38th St.



Picture 3 Glenwood Looking South at Chinden Blvd




Picture 4 End of Sidewalk 38th Street



Picture 5 End of North Side of Franklin Sidewalk West of Improvements at Cole and Franklin



Picture 6 Chinden Blvd End of Bike Lane



Picture 7 Glenwood Looking South at Chinden Blvd.



Picture 8 Sidewalk Missing on 38th Street